







	Supply Connections	High Pressure Connection	Inspection Ports
	P & T	H	I1 & I2
1	1 1/4" BSPP	1 1/4" BSPP	1/8" BSPP



Function Diagram: 6DW-104-0_

Material	Changes	Date	Name	Issue	Material Code No.
					Finish
					Break all edges
					Hardening depth
					HV
Designer	Leif Hansen	Scale 1:3	Format A2	2x HC6DW in Parallel	P2W-HC6DW-_-_-1_
Approved by	<i>[Signature]</i>				
Date	20-02-2025			Assembly Drawing	Drawing No.: 6DW-126-00

